



# Typical Excavation of Unstable Fillslope on a Decommissioned Road

**Before**



**After**



**Pacific Watershed Associates Inc.**

Geologic and Geomorphic Studies • Watershed Restoration • Wildland Hydrology • Erosion Control • Environmental Services  
PO Box 4433, Arcata, CA 95518 / Ph: 707-839-5130 / FAX: 707-839-8168 / [www.pacificwatershed.com](http://www.pacificwatershed.com)